











Enviro All-in-One

Residential search report

Specimen Address, Specimen Town

Summary of risks identified

	Coal Mining Page 6	Known coal or potential mining risks within the property area	Further action
	Other Ground Stability Page 18	The property may have potential for natural/non-natural ground subsidence	Identified
	Contaminated Land Page 12	The property could be investigated further as potentially Contaminated Land	Action Required
	Flood Risk Page 14	The property is considered to have a risk of flooding	High
	Radon Page 20	The property lies within a Radon Affected area.	Identified
	Energy Page 22	Identified	Full assessments for these risks are available in other Groundsure searches including the Groundsure Avista 7 in 1 report. Contact Groundsure or your search provider for further details.
	Transportation Page 24	Identified	
	Planning Applications Page 25	Identified	

It is important to be fully informed of all risks associated with a property before completing your purchase. Please read all the information in this report carefully.

Overview of findings and recommendations

Coal Mining

According to the records held by the Coal Authority at the time the report was produced, the search report has identified evidence, or the potential of, coal mining related risks. For detailed findings please read from **page 6**.

Further action is required because there is evidence of:

- Mine entries within, or within 20 metres of the subject property

Further recommended reports

Based on the findings, the following reports are available which give more information on the risks identified:

Mine entry interpretive report
Mine entry plan and data sheets

For further help please contact our Mining Reports team on 0345 762 6848.

Environmental Findings

These relate to environmental risks that may affect the enjoyment of the property, health, insurance premiums, property values and/or a lender's willingness to lend.

Key recommended next steps:

- if the property was built after 1999, you can find out if its NHBC Buildmark Certificate includes contaminated land cover by emailing a copy of the NHBC certificate to info@groundsure.com, quoting your report reference. If so, our experts will review your report free of charge and, if appropriate, revise to a pass free of charge
- investigate the insurance on offer for the property to ensure any implications on premiums are fully understood before completion
- if the property was built after 1985, consider contacting the planning department of the relevant local authority to clarify any conditions placed in the original planning consent documentation regarding investigation/remediation (cleaning) of contamination on the site. Our experts will review any such conditions identified and if appropriate revise to a pass free of charge
- consider contacting the Contaminated Land Officer within the Environmental Health Department of the relevant Local Authority to ask about previous land use of the area, written details confirming whether the land has been designated 'Contaminated Land' (as defined under Part 2A of EPA 1990), and if the Local Authority plans to take any further action

- if speed is a priority, or other methods have failed, insurance might be the best option. However, at this stage it may be expensive, and it is not always possible to get suitable insurance. Numerous companies offer environmental insurance. If you are considering this option you can get in touch with Groundsure who will be happy to provide further details

Flood risk

The property is assessed to have a flood risk rating of moderate or higher. Key recommended next steps:

- consider flood prevention measures that may be useful in the property, such as flood gates and barriers or airbricks
- check to see if the property is eligible for the Flood Re scheme, which enables many properties at risk of flooding to be insured at reasonable rates: <http://www.floodre.co.uk/homeowner/about-us/>
- investigate the insurance on offer for the property to ensure any implications on premiums are fully understood before completion

Groundwater

The property is assessed to have a groundwater flood risk of moderate or higher. Key recommended next steps:

- if the house has a basement or other section below ground, investigate whether tanking is possible. This is a process where basement areas are sealed with a watertight material to prevent groundwater seeping in
- look at the search result in the context of its locality. Discuss with the seller (and potentially their neighbours) to see if groundwater flooding is common there and what measures are in place to combat it
- consider property level flood prevention measures that may be useful in the property, such as flood gates and barriers or airbricks
- consider conducting a visual check at the property looking for water staining, damp patches or mould growth. Be aware of any damp smells. It is also worth checking the survey to see if any of these things have been reported
- further advice on groundwater flooding has been produced by the Environment Agency and the Local Government Association and can be found at https://www.gov.uk/government/uploads/system/uploads/attachment_data/file/297421/flho0911bugi-e-e.pdf

Other Ground Stability

The property is assessed to lie within an area that either has a moderate to high risk of natural ground subsidence, a risk of natural cavities being present, or non-natural ground subsidence risks are present. Key recommended next steps:

- consider having a structural survey conducted by a Structural Surveyor to determine whether or not the property is affected. Note that any such structural survey will supersede the Groundsure report
- consider conducting a visual check at the property looking out for cracks and other signs of subsidence
- consider contacting the relevant Local Authority to ask for records of the property and local area relating to subsidence
- remember that professional advice should be sought before altering the ground in any way at the property, including by planting trees

Infilled Land

The property is assessed to lie within 25m of an area of infilled land. Key recommended next steps:

- consider having a structural survey conducted by a Structural Surveyor to determine whether or not the property is affected. Note that any such structural survey will supersede the Groundsure report
- consider conducting a visual check at the property looking out for cracks and other signs of subsidence, however be aware recent redecoration of the property may mask signs
- consider contacting the relevant Local Authority to ask for records of the property and local area relating to subsidence
- remember that professional advice should be sought before altering the ground in any way at the property, including planting trees
- if structural surveys have not considered the potential effects of being built on a site like this, you may wish to contact the local Building Regulations Officer, Planning Department and if recently constructed, the site developers. Newer developments may benefit from an NHBC guarantee or other environmental warranty that often covers structural issues
- unless information is available confirming that suitable ground engineering techniques have been used to protect the property, it is recommended that you contact the Local Authority Planning department to confirm whether protective design measures were used during construction

Radon

The property lies within a radon Affected Area, where at least 1% of properties are affected. Key recommended next steps:

- if the property is new build, you can check compliance on radon protection with the developer
- if testing has not been carried out, it would be a sensible precaution to arrange for the property to be tested with radon detectors. If initial short-term radon screening tests are inconclusive, or the purchaser would prefer to carry out a full three-month test, it may be possible to arrange a 'radon bond'. See for example <http://www.radonassociation.co.uk/guide-to-radon/information-for-house-buyers-and-sellers/> for further information
- high levels of radon can be reduced through carrying out remedial works to the property. See for example <http://www.radonassociation.co.uk/guide-to-radon/information-for-house-buyers-and-sellers/> for further details

Other considerations

No additional factors that Groundsure believe require further action have been identified in relation to the property.

Environmental summary



Environmental searches are designed to ensure that significant hazards and risks associated with this property are identified and considered alongside the investment in or purchase of a property.

Please see the guidance section on **page 2** for further advice.

Contaminated Land

Our Contaminated Land searches have found some potentially significant contamination risks. These could include risks relating to industrial processes, petrol stations, or landfill.

Please see **page 12** for further details of the identified issues.

Past Land Use	Identified
Waste and Landfill	Passed
Current Industrial	Passed

Flood Risk

The property and area within the site outline is at risk from one or more kinds of flooding. Property's overall risk assessment for river, coastal, surface water and groundwater flooding is high.

Further explanation of flood risk assessment can be seen here [groundsure.com/understanding-flood-risk](https://www.groundsure.com/understanding-flood-risk)

River and Coastal Flooding	High
Groundwater Flooding	High
Surface Water Flooding	Significant
Past Flooding	None
Flood Storage Areas	None

Floodability Rating

Amber

The rating is compiled by JBA, the UK's leading flood expert. Please see **page 27**

Other Ground Stability

The property is assessed to have potential for natural or non-natural ground subsidence.

Please see **page 18** for further details of the identified issues.

Natural Ground Stability	Moderate - High
Non-Natural Ground Stability	Identified

Radon

The property is in a radon Affected Area. This could mean that inhabitants are at risk from the harmful effects of radon. Percentage of affected homes in your local area is between 1% and 3%.


Please see **page 20** for further details of the identified issues.

In a radon Affected Area

Coal mining



This report is based on, and limited to, the records held by the Coal Authority and the Cheshire Brine Subsidence Compensation Board's records, at the time we answer the search.



Key

Approximate position of enquiry boundary shown



Disused adit



Disused mineshaft



Coal claims



Licensee claims



Brine claims



© Crown copyright and database rights 2018
 Ordnance Survey Licence number: 100020315

Detailed findings

1. Past underground coal mining

The property is not within a surface area that could be affected by recorded past underground mining.

However the property is in an area where the Coal Authority believe there is coal at or close to the surface. This coal may have been worked at some time in the past. The potential presence of coal workings at or close to the surface should be considered prior to any site works or future development activity. Please refer to the Comments section of this report for further information.

The property is in a surface area that could be affected by underground mining in 1 seam of ironstone at 60m depth, and last worked in 1848.

2. Present underground coal mining

The property is not within a surface area that could be affected by present underground mining.

3. Future underground coal mining

The property is not in an area where the Coal Authority has plans to grant a licence to remove coal using underground methods.

The property is not in an area where a licence has been granted to remove or otherwise work coal using underground methods.

The property is not in an area likely to be affected from any planned future underground coal mining.

However, reserves of coal exist in the local area which could be worked at some time in the future.

No notices have been given, under section 46 of the Coal Mining Subsidence Act 1991, stating that the land is at risk of subsidence.

4. Mine entries

Within, or within 20 metres of, the boundary of the property there are 3 mine entries, the approximate positions of which are shown on the enquiry boundary plot.

Our records disclose the following information:

397298-012. was grouted by M & J Drilling Services Limited for J S Bloor Limited in 1988

397298-013. an investigation by probe drilling by M & J Drilling Services Limited for J S Bloor Limited in 1988 found no evidence of the mine shaft

397298-014. an investigation by probe drilling by M & J Drilling Services Limited for J S Bloor Limited in 1988 found no evidence of the mine shaft

For an additional fee, the Coal Authority can provide a Mine Entry Interpretive Report. The report will provide a separate assessment for the mine entry/entries referred to in this report. It gives an opinion on the likelihood of mining subsidence damage caused from ground movement as a consequence of the mine entry/entries. It also gives details of the remedies available for subsidence damage where the mine entry was sunk in connection with coal mining.

Please note that it may not be possible to produce a report if the main building to the property cannot be identified from Coal Authority plans (ie for development sites and new build).

For further advice on how to order this additional information please visit www.groundstability.com.

5. Coal mining geology

The Coal Authority is not aware of any damage due to geological faults or other lines of weakness that have been affected by coal mining.

6. Past opencast coal mining

The property is not within the boundary of an opencast site from which coal has been removed by opencast methods.

7. Present opencast coal mining

The property does not lie within 200 metres of the boundary of an opencast site from which coal is being removed by opencast methods.

8. Future opencast coal mining

There are no licence requests outstanding to remove coal by opencast methods within 800 metres of the boundary.

The property is not within 800 metres of the boundary of an opencast site for which a licence to remove coal by opencast methods has been granted.

9. Coal mining subsidence

The Coal Authority has not received a damage notice or claim for the subject property, or any property within 50 metres of the enquiry boundary, since 31 October 1994. There is no current Stop Notice delaying the start of remedial works or repairs to the property.

The Coal Authority is not aware of any request having been made to carry out preventive works before coal is worked under section 33 of the Coal Mining Subsidence Act 1991.

10. Mine gas

The Coal Authority has no record of a mine gas emission requiring action.

11. Hazards related to coal mining

The property has not been subject to remedial works, by or on behalf of the Coal Authority, under its Emergency Surface Hazard Call Out procedures.

12. Information from the Cheshire Brine Subsidence Compensation Board

The property lies outside the Cheshire Brine Compensation District.

Comments on the Coal Authority information

The boundary plot shows the approximate location of the disused mine entry/entries referred to in this report. For reasons of clarity, mine entry symbols may not be drawn to the same scale as the plan.

Property owners have the benefit of statutory protection (under the Coal Mining Subsidence Act 1991*). This contains provision for the making good, to the reasonable satisfaction of the owner, of physical damage from disused coal mine workings including disused coal mine entries. A leaflet setting out the rights and obligations of either the Coal Authority or other responsible persons under the 1991 Act can be obtained by visiting www.groundstability.com.

If you wish to discuss the relevance of any of the information contained in this report, you should seek the advice of a qualified mining engineer or surveyor. If you or your advisor wish to examine the source plans from which the information has been taken, these are available to view, free of charge, at our Head Office in Mansfield. To book an appointment please ring 01623 637225. Should you or your advisor wish to carry out a physical investigation that may enter, disturb or interfere with any disused mine entry, prior permission of the owner must be sought. For coal mine entries, the owner will normally be the Coal Authority.

The Coal Authority, regardless of responsibility and in conjunction with other public bodies, provide an emergency call out facility in coalfield areas to assess the public safety implications of mining features (including disused mine entries). Our emergency telephone number is 01623 646333.

*Note, this Act does not apply where coal was worked or gotten by virtue of the grant of a gale in the Forest of Dean, or any other part of the Hundred of St. Briavels in the county of Gloucester.

In view of the mining circumstances a prudent developer would seek appropriate technical advice before any works are undertaken.

Therefore if development proposals are being considered, technical advice relating to both the investigation of coal and former coal mines and their treatment should be obtained before beginning work on site. All proposals should apply good engineering practice developed for mining areas. No development should be undertaken that intersects, disturbs or interferes with any coal or mines of coal without the permission of the Coal Authority. Developers should be aware that the investigation of coal seams/ former mines of coal may have the potential to generate and/or displace underground gases and these risks both under and adjacent to the development should be fully considered in developing any proposals. The need for effective measures to prevent gases entering into public properties either during investigation or after development also needs to be assessed and properly addressed. This is necessary due to the public safety implications of any development in these circumstances.

Additional remarks

Information provided by the Coal Authority in this report is compiled in response to the Law Society's CON29M Coal Mining and Brine Subsidence Claim enquiries. The said enquiries are protected by copyright owned by the Law Society of 113 Chancery Lane, London WC2A 1PL. Please note that Brine Subsidence Claim enquiries are only relevant for England and Wales. This report is prepared in accordance with the Law Society's Guidance Notes 2006, the User Guide 2006 and the Coal Authority and Cheshire Brine Board's Terms and Conditions applicable at the time the report was produced.

If this Report is for a residential property, insurance is included to cover any loss in property value caused by any changes in the information contained in this report. Please see the attached certificate of insurance for the terms and conditions of this insurance. The insurance does not cover non-residential property or interpretive reports.

Disclaimer

The Coal Authority owns the copyright in this report and the information used to produce this report is protected by our database rights. All rights are reserved and unauthorised use is prohibited. If we provide a report for you, this does not mean that copyright and any other rights will pass to you. However, you can use the report for your own purposes.

Alternative formats

If you would like this report in an alternative format, please contact our communications team.

Coal & Brine Search Report Insurance Policy



On behalf of the insurer

Schedule

Policy number: **25560562**

The insurer: **Liberty Legal Indemnities – underwritten by Liberty Mutual Insurance Europe Limited**

Binding Authority contract number: **RNMFP1803841**

Property: **Specimen Address, Specimen Town**

Reference: **81002290017001**

Limit of cover: **£50,000**

Dated: **3 April 2018**

This policy and schedule shall be read together and any word or expression to which a specific meaning has been attached in either shall bear such meaning wherever it may appear.

Where an Coal & Brine Search Report has been obtained in connection with a sale of the property, cover is provided for the benefit of a purchaser and their lender; in the case of a re-mortgage or where the existing owner chooses to obtain an Coal & Brine Search Report, cover is provided for the benefit of the owner and their lender.

The policy offers protection against loss sustained by the owner of the property if any new problems or adverse entries are revealed in a subsequent Coal & Brine Search Report which were not revealed by the original report to which the policy was attached.

The insured shall at all times comply with the requirements of the Conditions of this Policy.

Coal & Brine Search Report Terms and Conditions can be viewed online at this link:

<https://testing.groundstability.com/insurance/terms/20170428/terms.html>

Contaminated Land



© Crown copyright and database rights 2018. Ordnance Survey licence 100035207

Past Land Use

Previous use of industrial land

The land on or near the property has been subject to previous industrial activity. This risk of contamination could affect your ability to get a mortgage or, if the land is found to be contaminated, could entail a legal obligation and associated costs to rectify.

As our searches suggest industrial activities at the property may have caused soil or groundwater contamination, further enquiries or insurance is recommended. Groundsure's experts can help you with this.

Please see the guidance section on **page 2** for further advice.

Distance	Direction	Use	Date
0	on site	Unspecified Works	1955

Enviro All-in-One

Coal Authority ref: 81002290017001

Report ref: 71003170616001

Your ref: -

Grid ref: 397230 298787

Date: 3 April 2018

Distance	Direction	Use	Date
0	on site	Unspecified Works	1968
0	on site	Unspecified Works	1974
0	on site	Unspecified Foundry	1978

The area is classified as 'High Potential Risk' of designation as Contaminated Land under the Environmental Protection Act 1990.

For any coal mining related issues please contact the Coal Authority:

0345 762 6848
groundstability@coal.gov.uk


For all other issues and assistance please contact Groundsure:

0844 415 9000
info@groundsure.com

Flood



Risk of flooding from rivers and the sea



Risk of flooding from rivers and the sea

The property has a High chance of flooding in any given year, according to Risk of Flooding from Rivers and Sea (RoFRaS) data. This could cause problems with insuring the property against flood risk. However, if built before 2009, it may be eligible for insurance assistance from the Flood Re scheme: <http://www.floodre.co.uk/>


RoFRaS assesses flood risk from rivers and the sea in England and Wales, using local data and expertise. It shows the chance of flooding from rivers or the sea, taking account of flood defences and the condition those defences are in. The RoFRaS model uses local water level and flood defence data to model flood risk. See below for explanation of the RoFRaS levels of flood risk.

Please see the guidance section on **page 2** for further advice.

Environment Agency RoFRaS risk ratings

Very Low	Low	Medium	High
The chance of flooding from rivers or the sea is considered to be less than 1 in 1000 (0.1%) in any given year.	The chance of flooding from rivers or the sea is considered to be less than 1 in 100 (1%) but greater than or equal to 1 in 1000 (0.1%) in any given year.	The chance of flooding from rivers or the sea is considered to be less than 1 in 30 (3.3%) but greater than 1 in 100 (1%) in any given year.	The chance of flooding from rivers or the sea is considered to be greater than or equal to 1 in 30 (3.3%) in any given year.

Surface water flood risk



Surface water flood risk

The property is likely to be prone to flooding following extreme rainfall, which could cause problems with insuring the property against flood risk. However, if it was built before 2009, it may be eligible for insurance assistance from the Flood Re scheme.

The area in which the property is located has been assessed to be at Significant risk of surface water flooding. This area is considered to have a 1 in 75 probability of surface water flooding due to rainfall in a given year to a depth of between 0.3m to 1m. However, as is the case with probability statistics and predictions, this information should be used as a guideline only. The area may flood several years in row, or not at all for many

many years.

These risk calculations are based on Jeremy Benn Associate (JBA) Risk Management maps.

Groundwater Flooding



JBA Risk Management data indicates that the property is in an area with a High risk of groundwater flooding. Groundwater levels are either at or very near (within 0.025m of) the ground surface. Within this zone there is a risk of groundwater flooding to both surface and subsurface assets. Groundwater may emerge at significant rates and has the capacity to flow overland and/or pond within any topographic low spots.


Groundwater flooding is flooding caused by unusually high groundwater levels. It occurs as excess water emerging at the ground surface or within underground structures such as basements. Groundwater flooding tends to be more persistent than surface water flooding, in some cases lasting for weeks or months, and it can result in significant damage to property. This risk assessment is based on a 5m Digital Terrain Model (DTM) and a 1 in 100 year return period.

Some of the responses contained in this report are based on data and information provided by the Natural Environment Research Council (NERC) or its component body the British Geological Survey (BGS). Your use of any information contained in this report which is derived from or based upon such data and information is at your own risk. Neither NERC nor BGS gives any warranty, condition or representation as to the quality,

accuracy or completeness of such information and all liability (including for negligence) arising from its use is excluded to the fullest extent permitted by law. Your use of the data/report/assessment constitutes your agreement to bring no claim against NERC or BGS in connection with it.

SAMPLE

Other ground stability




Natural ground subsidence

The property, or an area within 50m of the property, is at a moderate to high degree of risk of natural ground subsidence. This kind of structural risk can cause problems at a property in the long term and may entail costs to resolve.

Please see the guidance section on **page 2** for further advice.

Surveyors are normally aware of local problem areas in relation to subsidence, however, this data provided by the British Geological Survey (BGS) can highlight areas where a significant potential for natural ground subsidence exists and whether it may need particular consideration. The term "Subsidence" refers to ground movement that could cause damage to foundations in domestic or other properties.

Non-natural ground subsidence



Ground cavities filled with other materials



Maps suggest the property is located on a previous pond, quarry, mine, landfill or other hole in the land. These land cavities are often filled in with various materials and this can cause structural problems, although such events are rare. Groundsure's experts recommend that you check whether your structural surveys have taken this into account.

Please see the guidance section on **page 2** for further advice.

Distance	Direction	Use	Date
0	on site	Unspecified Ground Workings	1921
3 m	NW	Gravel Pit	1885
5 m	N	Unspecified Ground Workings	1913
5 m	NW	Gravel Pit	1885
5 m	N	Sand Pit	1901

Groundsure's experts systematically analyse historical maps, which can highlight areas that, over time, may have been filled with various materials. The materials used are usually safe, although in some cases contaminative materials may also have been used. Past mining activity was identified from systematic analysis of Ordnance Survey historical maps. Information is taken from features identified on maps, which do not indicate the distance or direction that mines extend beneath the surface. For example, features such as mine shafts only indicate the entrance to a mine. From this, we may infer the potential for underground features to extend outward from this point. Some features within this database may also relate to non-mining underground activities e.g. air shafts for underground railways.

Radon



The property is in a radon Affected Area, meaning the area has a general radon level above the radon Action Level. This does not necessarily mean there is a radon problem in the property itself, to establish that a radon measurement in the building must be conducted. Public Health England (PHE) provides a radon testing service that can be accessed at www.ukradon.org. Radon is a colourless, odourless radioactive gas present in all areas of the United Kingdom, usually at levels that pose a negligible risk to homebuyers. However, the property is situated in an area where levels of radon can be much higher and pose a health risk. High levels of radon can

cause lung cancer, particularly for smokers and ex-smokers. The higher the level and the longer the period of exposure, the greater the risk. If you are buying a currently occupied property in a radon Affected Area, ask the present owner whether radon levels have been measured and, if they have, whether the results were above the radon Action Level. If so, what remedial measures were installed, were radon levels re-tested and did the re-testing confirm the measures has been effective. Further information on radon is available from PHE or www.ukradon.org

Please see the guidance section on **page 2** for further advice.

Energy summary



The property has been identified to lie within 5km of one or more energy features. The Enviro-All-in-One report summarises these on this page.

If required, full details on these energy features including a detailed location plan relative to the property can be available when you purchase a Groundsure Energy report or the comprehensive Groundsure Avista report via your preferred searches provider.

Oil and Gas

No active or planned wells or extraction areas (such as fracking sites) identified near the property.

Oil and Gas Areas
Oil and Gas Wells

None
None

Wind and Solar

Our search of existing and planned renewable wind and solar infrastructure has identified results.

Wind
Solar

Identified
None

Energy Infrastructure

Our search of major energy transmission or generation infrastructure and nationally significant infrastructure projects has identified results.

Power stations
Energy Infrastructure
Projects

None
Identified
None

Electricity transmission lines



Electricity transmission lines and pylons

The nearest overhead transmission lines and/or pylon is located 483m from the property.

Overhead power transmission lines are known to emit electromagnetic fields (EMF). For further information on issues associated with transmission lines you may wish to contact the EMF Unit Public Information Line on 0845 7023270 or visit www.emfs.info. Guidance on electromagnetic fields resulting from transmission and distribution lines can also be found on the Public Health England (PHE) website.

Groundsure provide the data for information only and do not make any judgment on the risks or otherwise of EMFs. However, if the existence of overhead power transmission may have a material impact with regard to the decision to purchase the property, Groundsure recommends contacting these organisations.

Transportation summary



The property has been identified to lie within the search radius of one or more transportation features detailed below.

If required, full details on these transportation features including a detailed location plan relative to the property can be available when you purchase a Groundsure HS2 and Crossrail report or the comprehensive Groundsure Avista report via your preferred searches provider.

HS2

No results for Phase 1 or Phase 2 of the HS2 project (including the 2016 amendments) have been identified within 2.5km of the property. However, HS2 routes are still under consultation and exact alignments may change in the future.

HS2 Route	None
HS2 Safeguarding	None
HS2 Stations	None
HS2 Depots	None

Crossrail 1

The property is not within 250 metres of the Crossrail project.

Crossrail 1 Route	None
Crossrail 1 Stations	None
Crossrail 1 Worksites	None

Railways

The property is not within 250 metres of any railways or railway stations.

For further information on historical railways and tunnels and Underground features, purchase a Groundsure Underground report via your searches provider.

Active Railways	None
Historical Railways and Tunnels	Identified
Railway and Tube Stations	None
London Underground and DLR	None

Planning summary



Planning Applications

Using Local Authority planning information supplied and processed by Glenigan dating back 10 years, this information is designed to help you understand possible changes to the area around the property. Please note that even successful applications may not have been constructed and new applications for a site can be made if a previous one has failed. We advise that you use this information in conjunction with a visit to the property and seek further expert advice if you are concerned or considering development yourself.

5 Total applications

This total includes large developments within 250 m, small developments within 75 m and house extensions within 50 m. If required, full details on these applications including a detailed location plan relative to the property can be available when you purchase a Groundsure Planning Report or the comprehensive Groundsure Avista report via your preferred searches provider.

Planning constraints

No protected areas have been identified within 50 metres of the property. Protected areas include nature reserves and other conservation areas.

Environmental Protected Areas	None
Visual and Cultural Protected Areas	None

Telecoms

There are no mobile masts, mobile phone base stations or planning applications for mobile masts identified within 500 metres of the property.

Mobile phone masts	None
---------------------------	-------------

Additional searches that are not of concern or relevant to this location

The searches listed below were run against the property and found not to be of concern or represent a risk.

Contaminated Land

Potential contamination from storage tanks
Previous power station, substation, or other energy feature
Previous petrol stations
Previous garages
Land previously used for military purposes
Previous landfill (from British Geological Survey records, 1973)
Previous landfill (from Local Authority and historical mapping records)
Waste site no longer in use
Active or recent landfill
Previous landfill (from Environment Agency Records)
Active or recent waste sites
Active industrial land use
Active or obsolete petrol stations
Site storing large quantities of hazardous or explosive substances
Hazardous substance storage/usage
Sites designated as Contaminated Land
Licence for pollutant release
Current and recent pollutant release to water or land
Pollutant release licence to air
Licence for release of Red List toxic substances
Specific intent to release exceptionally toxic liquids
Dangerous Substance Inventory (List 1)
Dangerous Substance Inventory (List 2)
Recorded pollution incidents

Registered Parks and Gardens

Planning

Mobile phone masts
Mobile phone masts planning records

Flood

Flood storage areas: part of floodplain
Historic flood areas
Areas benefiting from flood defences
Flood defences
Proposed flood defences

Ground stability

Natural geological cavities
Non-coal mining
Mining cavities

Planning constraints

Sites of Special Scientific Interest (SSSI)
Internationally important wetland sites (Ramsar sites)
Special Area of Conservation
Special Protection Areas (for birds)
National Nature Reserves
Local Nature Reserves
Designated Ancient Woodland
Green Belt
World Heritage Sites
Areas of Outstanding Natural Beauty
National Parks
Conservation Areas
Listed Buildings
Certificates of Immunity from Listing
Scheduled Monuments

JBA Floodability

The property has been rated as **Amber**. Please see the guidance section on **page 2** for further advice.

This rating is calculated by JBA and is based entirely on JBA's modelled river, coastal, pluvial and groundwater flood risk data. This data is used by a large number of top insurance companies in order to assess flood risk, though individual insurers may also have recourse to further information not used in this assessment such as claim history, and is indicative rather than definitive.

There are some exclusions to the Flood Re scheme and these include; commercial properties (including buy to let), new homes built after 1st January 2009 and blocks of flats with three or more units. Flood Re is designed to run for 25 years, to allow time for the Government, local authorities, insurers and communities to become better prepared for flooding. After this period, the market is expected to return to risk reflective pricing, and properties with flood risks that have not been mitigated may face significantly increased premiums and/or difficulty in obtaining cover.

The JBA Floodability Index is categorised on a fivefold scale and also includes a statement of the possibility of insurance companies ceding the property into the Flood Re scheme (subject to terms, applicant's status and individual insurers' approach to risk, historical flooding events at the property, exclusions to the Flood Re scheme and any other factors which may be relevant):

Green indicates a level of flood hazard such that insurance covering flood risk may be obtainable relatively easily as part of a standard household insurance contract. Very low possibility of insurance companies ceding the property into the Flood Re scheme unless the property has flooded in the past.

Amber indicates a level of flood hazard such that insurance covering flood risk may be available but may be subject to increased premiums and non-standard and/or additional terms. Low possibility of insurance companies ceding the property into the Flood Re scheme unless the property has flooded in the past.

Red indicates a level of flood hazard such that standard priced insurance covering flood risk may be more difficult to obtain. Low to moderate possibility of insurance companies ceding the property into the Flood Re scheme unless the property has flooded in the past.

Black 1 indicates a level of flood hazard such that standard priced insurance covering flood risk may be significantly more difficult to obtain. Moderate to high possibility of insurance companies ceding the property into the Flood Re scheme, especially if the property has flooded in the past.

Black 2 indicates a level of flood hazard such that standard priced insurance covering flood risk may be extremely difficult to obtain. High possibility of insurance companies ceding the property into the Flood Re scheme, especially if the property has flooded in the past.

Contaminated Land assessment methodology

As part of this report Groundsure provide a professional assessment of the risks posed by key environmental information which could lead to the property being designated as 'Contaminated Land' as defined under Part 2A of the Environmental Protection Act 1990. This assessment is based on the following data:

- historical land use (compiled from 1:10,000 and 1:10,560 maps)
- petrol stations, garages, energy features and tanks (compiled from 1:1,250 and 1:2,500 maps) – for selected areas.
- historic military / ordnance sites
- landfill and waste transfer/treatment or disposal sites (including scrap yards)
- current industrial uses (as defined by PointX data)
- Catalyst petrol station
- Part A(1), Part A(2) and Part B Authorisations
- Control of Major Accident Hazards Sites (COMAH) and Notification of Installations Handling Hazardous Substances (NIHHS)
- sites determined as Contaminated Land under Part 2A EPA 1990
- Planning Hazardous Substance Consents
- Environment Agency Recorded Pollution Incidents
- Dangerous Substances Inventory Releases (DSI)
- Red List Discharge Consent

The level of risk associated with the property is either Passed or In Need of Further Assessment. If the site is In Need of Further Assessment it does not necessarily mean that the site is unsuitable for purchase, but only that further assessment of the risk associated with the site is required.

Method Statement

In assessing specific site risk, Groundsure follows principles used extensively throughout the environmental consultancy sector. Our system looks at the potential for specific industries to have generated residual contamination and for this contamination to remain at a site, or to have migrated to neighbouring sites. Sites are scored based on this system and if a site scores highly it indicates a high level of risk.

Limitations of the Study

This screening process reviews historical mapping and a range of current databases. The historical land use database reviewed for this study does NOT include 1:2,500 or 1:1,250 scale maps except for Groundsure's additional information database of selected features namely tanks, energy features, petrol filling stations and garages. This additional information database covers the majority of the UK, but not all. Where 1:2500 or 1:1250 scale maps are utilised all relevant and available map epochs to Groundsure are used. Additionally, this review does NOT include specific enquiries to the Local Authority who may hold additional information and it does NOT include a site visit/inspection. Your attention is drawn to the Terms and Conditions of Groundsure Limited under which this service is provided.

Search Code and Groundsure terms and conditions

IMPORTANT CONSUMER PROTECTION INFORMATION

This search has been produced by Groundsure Ltd, Sovereign House, Church Street, Brighton, BN1 1UJ. Tel: 08444 159 000. Email: info@groundsure.com which is registered with the Property Codes Compliance Board (PCCB) as a subscriber to the Search Code. The PCCB independently monitors how registered search firms maintain compliance with the Code.

The Search Code

- provides protection for homebuyers, sellers, estate agents, conveyancers and mortgage lenders who rely on the information included in property search reports undertaken by subscribers on residential and commercial property within the United Kingdom
- sets out minimum standards which firms compiling and selling search reports have to meet
- promotes the best practice and quality standards within the industry for the benefit of consumers and property professionals
- enables consumers and property professionals to have confidence in firms which subscribe to the code, their products and services

By giving you this information, the search firm is confirming that they keep to the principles of the Code. This provides important protection for you.

The Code's core principles

Firms which subscribe to the Search Code will:

- display the Search Code logo prominently on their search reports
- act with integrity and carry out work with due skill, care and diligence
- at all times maintain adequate and appropriate insurance to protect consumers
- conduct business in an honest, fair and professional manner
- handle complaints speedily and fairly
- ensure that products and services comply with industry registration rules and standards and relevant laws
- monitor their compliance with the Code

Complaints Advice

If you have a query or complaint about your search, you should raise it directly with the search firm, and if appropriate ask for any complaint to be considered under their formal internal complaints procedure. If you remain dissatisfied with the firm's final response, after your complaint has been formally considered, or if the firm has exceeded the response timescales, you may refer your complaint for consideration under The Property Ombudsman scheme (TPOs). The Ombudsman can award compensation of up to £5,000 to you if the Ombudsman finds that you have suffered actual financial loss and/or aggravation, distress or inconvenience as a result of your search provider failing to keep to the Code.

Please note that all queries or complaints regarding your search should be directed to your search provider in the first instance, not to TPOs or to the PCCB.

TPO's Contact Details:

The Property Ombudsman scheme, Milford House, 43-55 Milford Street, Salisbury, Wiltshire SP1 2BP. Tel: 01722 333306 Fax: 01722 332296 Email: admin@tpos.co.uk Web: <https://www.tpos.co.uk/>

PLEASE ASK YOUR SEARCH PROVIDER IF YOU WOULD LIKE A COPY OF THE SEARCH CODE

COMPLAINTS PROCEDURE: If you want to make a complaint, we will:

- acknowledge it within 5 working days of receipt
- normally deal with it fully and provide a final response, in writing, within 20 working days of receipt
- keep you informed by letter, telephone or e-mail, as you prefer, if we need more time
- provide a final response, in writing, at the latest within 40 working days of receipt
- liaise, at your request, with anyone acting formally on your behalf

Complaints should be sent to:

Operations Director, Groundsure Ltd, Sovereign House, Church Street, Brighton, BN1 1UJ. Tel: 08444 159 000. Email:

info@groundsure.com If you are not satisfied with our final response, or if we exceed the response timescales, you may refer the complaint to The Property Ombudsman scheme (TPOs): Tel: 01722 333306, E-mail: admin@tpos.co.uk We will co-operate fully with the Ombudsman during an investigation and comply with their final decision.

Groundsure's Terms and Conditions can be viewed online at this link: <https://www.groundsure.com/terms-and-conditions-march-2018/>

Important consumer protection information

All of the advice and reports that Groundsure produces are covered by a comprehensive Remediation Contribution policy to ensure customers are protected, see <https://www.groundsure.com/remediation> for full details.

Data providers

Groundsure works with respected data providers to bring you the most relevant and accurate information in your Enviro-All-in-One report. To find out who they are and their areas of expertise see <https://www.groundsure.com/sources-reference>.